

# GE COMMERCIAL MOTORS Industrial Parts Catalog

## Axiparts Global Industrial RFQ Platform

Email: [info@axiparts.com](mailto:info@axiparts.com)

Website: <https://axiparts.com>

Premium RFQ catalog for GE COMMERCIAL MOTORS industrial spare parts, MRO components and replacement products. Every listed product is linked directly to its live RFQ product page.

**Brand:** GE COMMERCIAL MOTORS

**Listed Products in This PDF:** 27

**Catalog URL:** <https://axiparts.com/catalogs/brands/ge-commercial-motors.pdf>

| Part Number     | Product Description  | Live RFQ Link                         |
|-----------------|--|---------------------------------------|
| 00PPG000478400A | 00PPG000478400A old number, new 00PPG000558400A LÜFTERMOTOR                        | <a href="#">Open Product RFQ Page</a> |
| 102637          | 102637 HUB, DRIVING, RIGHT AXLE / Original Spare Part                              | <a href="#">Open Product RFQ Page</a> |
| 5KCP39EG        | 5KCP39EG ,S086AS MOTOR(INDOOR);HP-1/5, V-230, KW-14 SPLITA/C INDOOR MOTOR - 1/5HP; | <a href="#">Open Product RFQ Page</a> |
| 5KCP39FG        | 5KCP39FG (P642 S) (obsolete replaced by B13400269 SP) Original Spare Part          | <a href="#">Open Product RFQ Page</a> |
| 5KCP39JG        | 5KCP39JG ,S088AS   | <a href="#">Open Product RFQ Page</a> |
| 5KCP39JG3318E   | 5KCP39JG3318E Original Spare Part  | <a href="#">Open Product RFQ Page</a> |
| 5KCP39PG-R641   | 5KCP39PG-R641 S, CPN:B13400504   | <a href="#">Open Product RFQ Page</a> |
| 5kcp39rg        | 5kcp39rg s475bs motor  | <a href="#">Open Product RFQ Page</a> |
| 5KCP39SG        | 5KCP39SG MOTOR(INDOOR);HP-1/2, V-230, FLA-2.8                                      | <a href="#">Open Product RFQ Page</a> |
| 5KCP39SGS091AS  | 5KCP39SGS091AS LÜFTERMOTOR   | <a href="#">Open Product RFQ Page</a> |
| 5KH32GN5589X    | 5KH32GN5589X (alternative is HG450)  | <a href="#">Open Product RFQ Page</a> |
| 5KH32GN5602BX   | 5KH32GN5602BX MULTUPLEX MOTOR  | <a href="#">Open Product RFQ Page</a> |
| 5KH32GNB812AX   | 5KH32GNB812AX  | <a href="#">Open Product RFQ Page</a> |
| 5KH36MNA445X    | 5KH36MNA445X Carbonator motor  | <a href="#">Open Product RFQ Page</a> |
| 5KSP39NG        | 5KSP39NG electric motor  | <a href="#">Open Product RFQ Page</a> |
| B13400269       | B13400269 SP Original Spare Part   | <a href="#">Open Product RFQ Page</a> |
| C07J080104      | C07J080104 Electric motor  | <a href="#">Open Product RFQ Page</a> |
| E354G93092BMXJ  | E354G93092BMXJ KABEL, LÜFTERMOTOR  | <a href="#">Open Product RFQ Page</a> |
| GE              | GE 00PPG000007201A +E354G93092BMXJ(15 Motors+15 cables)                            | <a href="#">Open Product RFQ Page</a> |
| HC37AE196S      | HC37AE196S LÜFTERMOTOR   | <a href="#">Open Product RFQ Page</a> |
| HC41AE195S      | HC41AE195S LÜFTERMOTOR   | <a href="#">Open Product RFQ Page</a> |
| HC45AE195S      | HC45AE195S LÜFTERMOTOR   | <a href="#">Open Product RFQ Page</a> |

| Part Number | Product Description                              | Live RFQ Link                         |
|-------------|--|---------------------------------------|
| HC45AE196S  | HC45AE196S LÜFTERMOTOR                           | <a href="#">Open Product RFQ Page</a> |
| HG450       | HG450 (alternative for 5KH32GN5589X)             | <a href="#">Open Product RFQ Page</a> |
| MOD.        | MOD. 5KH32GNB812AX Motor                         | <a href="#">Open Product RFQ Page</a> |
| S091AS      | S091AS   | <a href="#">Open Product RFQ Page</a> |
| Type:       | Type: 5KCP39JGP866 S - OEM code: B13400249 Motor | <a href="#">Open Product RFQ Page</a> |

**Axiparts Offices**

Germany Head Office: Lise-Meitner-Straße 13, 89081 Ulm, Germany

USA Office: 16225 Park Ten Pl #500, Houston, TX 77084, United States

Dubai Office: HDS Business Centre Tower, Cluster M, 33rd Floor, Jumeirah Lake Towers, Dubai, United Arab Emirates